

Configuration summary

| Mat. no. | Description Order code | Quantity | Unit |
|----------|--------------------------------------|----------|------|
| 52017196 | Cerabar S PMC71 PMC71-ABR1H11GBAA | 1 | ST |

| | | | |
|-----|--------------------------------------|----|--|
| 010 | Approval: | A | Non-hazardous area |
| 020 | Output; Operating: | B | 4-20mA HART; inside + LCD |
| 030 | Housing; Cover Sealing; Cable Entry: | R | T17 316L hygiene IP66/68 NEMA6P;EPDM;M20 gland, T17 = side cover |
| 040 | Sensor Range; Sensor Overload Limit: | 1H | 1bar/100kPa/15psi gauge; 10bar/1MPa/150psi |
| 050 | Calibration; Unit: | 1 | Sensor range; mbar/bar |
| 070 | Process Connection: | 1G | Thread ISO228 G1-1/2, 316L, flush mount |
| 080 | Seal: | B | EPDM |
| 100 | Additional Option 1: | A | Not selected |
| 110 | Additional Option 2: | A | Not selected |